



A Meridian Life Science® Company

CHANGES TO MSDS STATUS

HyperLadder 50bp	BIO-33054	100 Lanes
HyperLadder 50bp	BIO-33039	200 Lanes
HyperLadder 50bp	BIO-33040	500 Lanes

Dear User,

Due to following Directives, the above mentioned product(s) do not require a Material Safety Data Sheet (MSDS).

European Union Directives 67/548/EC and 1999/45/EC
OSHA 29CFR1910.1200
Commonwealth of Australia [NOHSC:1005,1008(1999)]

Since the above mentioned Bioline product(s) contains <1% of a hazard classified component or <0.1% of a carcinogenic classified component, an MSDS is not required. Bioline always recommends taking suitable precautions when working with this product or indeed any biochemical reagent. Such precautions may include Personal Protective Equipment, such as a laboratory coat, gloves and eye protection.

Bioline may not be held liable for any injury or damage resulting from the handling or from contact with the Bioline product(s) listed above.

For further information please contact our Quality Assurance department at MSDS@bioline.com.

Bioline

