



A Meridian Life Science® Company

CHANGES TO MSDS STATUS

EPIK Biofluid miRNA Panel Lo-ROX Plate 0.1Y	BIO-66037	2 x 2 Plate
EPIK Biofluid miRNA Panel Lo-ROX Plate 0.2Y	BIO-66039	2 x 2 Plate
EPIK Biofluid miRNA Panel Lo-ROX Plate 0.1X	BIO-66042	2 x 2 Plate

Dear User,

Due to following Directives the above mentioned products do not require a Material Safety Data Sheet (MSDS).

European Union Directives 67/548/EC and 1999/45/EC
OSHA 29CFR1910.1200
Commonwealth of Australia [NOHSC:1005,1008(1999)]

This is due to the product containing <1% of a hazard classified component or <0.1% of a carcinogenic classified component. For these reasons a MSDS has not been provided. Bioline Reagents Ltd. always recommend that when working with this or any other chemical suitable Personal Protective Equipment should be used, such as a laboratory coat, gloves and eye protection. Bioline Reagents Ltd. shall not be held liable for any damage resulting from the handling of or from contact with the above named product.

For further information please contact our Quality Assurance department at MSDS@bioline.com.

Best regards,

Bioline Reagent Ltd.

